

RELEASE NOTES

EFI™ is pleased to announce the release of Fiery® proServer and Fiery XF 6.3.1. This latest release is free of charge for all users with their Fiery XF software or Fiery proServer covered under an EFI Software Maintenance and Support Agreement, (SMSA), or an EFI Enhanced Service Program, (ESP).

Release overview:

- This update contains bug fixes and minor improvements for Fiery proServer and Fiery XF 6.3.

Client fixes:

- Fixed a media length correction issue for step and repeat scenarios.
- Fixed an issue that would prevent users from saving an updated export path for the EFI Rastek T660.
- Fixed a nesting issue where occasional freezing could occur while processing.
- Fixed an issue that would cause jobs to be resized if a “print head control bar” was added to a job.
- Fixed an issue where incorrect resizing of PostScript files could occur.
- Fixed a cut contour offset issue that occurred when the distance between cut marks was set to a specific minimum value.

Printer driver fixes:

- Fixed a backwards compatibility and color consistency issue that caused color shifts in Fiery XF 6.3 for EFI VUTEK printers when EPLs from older versions were used in Fiery XF 6.3.
- Fixed an error that occurred when printing a linearization chart on the EPSON SC-P100x0 printer in 300x600 dpi resolution.
- Removed the Canon imagePROGRAF PRO-1000, 2000, 4000, 4000s and 6000 printer drivers from Fiery XF 6.3 – these will officially be re-introduced in Fiery XF 6.4 and were not meant to be released in version 6.3.
- Fixed an EPSON Stylus Pro 7900 verification label issue.
- Fixed an issue with the automatic profile download feature of the HP Latex 360 printer.
- Fixed an EPSON SureColor SC-100X00/200X00 printer driver issue that would prevent users from printing multiple copies of jobs when the working color space was set to RGB.

Integration fixes:

- Fixed a bi-directional communication crash for the EFI H1625.

Color Tools fixes:

- Solved a problem that occurred when users double-clicked certain features in Color Tools.
- Fixed a total ink limit chart issue that would occur using the X-Rite iSis when connected via USB when running on a Mac OS X platform.
- Fixed a connection problem with the Barbieri LFP in Color Tools and Color Editor running on a Mac OS X platform.
- Fixed an issue with the “Finish” button not appearing correctly in the re-linearization step window.

Color Editor fixes:

- Fixed a bad default gradation curve issue that affected spot color reproduction.
- Fixed various Adobe PDF Print Engine issues.
- Fixed a spot color extraction issue that would occur for some PDF files.

Licensing fixes:

- Fixed an output license issue for the EFI H2000 Pro.

Availability:

- Fiery XF 6.3.1 is available as an online update for all configurations of Fiery proServer and Fiery XF version 6.3.

EFI Software Maintenance & Support Agreement (SMSA) and EFI Enhanced Service Program (ESP):

The EFI Software Maintenance & Support Agreement (SMSA) and the Enhanced Service Program (ESP) for Fiery XF and Fiery proServers provide an ongoing stream of features, improvements, fixes and the latest printer drivers. Fiery XF 6.3.1 is available at no extra charge for everyone with their software covered under one of these agreements.

For more information contact your local Fiery XF or Fiery proServer dealer or visit www.efi.com/fiery-for-inkjet. EFI's portfolio of integrated solutions increase productivity and improve your bottom line. Find out more at www.efi.com.

