

RELEASE NOTES

EFI™ is pleased to announce the release of Fiery® proServer and Fiery XF 7.0.2.

This latest release is free of charge for all users.

Bug fixes:

- Cutting-related fixes:
 - Fixed a mismatching default rotation between Fiery XF and the Zünd Cut Center.
 - The EPSON® driver's Autocut feature is now set to On by default again.
 - Fixed a missing and newly introduced Name variable which is designed to point to the barcode ID for Zünd Cut Center integration. Without it, the Zünd Cut Center was not able to complete barcode scanning.
 - Fixed a rare issue that could leave Fiery Command WorkStation® in an unresponsive state if users attempted to create a Step and Repeat in conjunction with Top & Bottom barcodes.
- Printer-related fixes:
 - Fixed some missing media formats for the Epson SureColor SC-T5200.
 - Corrected the maximum output width of the EFI™ VUTEK® 5r to 209 inches.
 - Fixed a truncated job ticket on EFI VUTEK FabriVU printers that could occur if users worked with media size corrections.
- PDF-related fixes:
 - Fixed a PDF interpretation error that could cause trim boxes and art boxes to be moved to a wrong position.
 - Fixed an issue that would prevent users from printing to PDF if a control bar was used.
- Fiery XF Universal Driver-related fixes:
 - Fixed a Fit to Width issue in conjunction with job labels when jobs were transmitted to the Fiery XF server through the Fiery XF Universal Driver.
 - Several white ink-related fixes.
 - Fixed an issue that would prevent users from generating exactly 100% white ink along with a job.
- Backup-related fixes:
 - Fixed a backup issue that would occur if media profiles were included in the *.icm as opposed to the *.icc format.
 - Resolved various color-related issues.
 - Fixed an issue that would lead to empty separations files if users applied a visual correction curve (.vcc) specifically to the spot color white ink.
 - Fixed an issue that broke color optimizations on the Epson SC-P5000.
- Fiery proServer-specific fixes:
 - Fixed an issue with Fiery proServers statically taking the IP address 10.10.100.1 without any chance for users to change it.

Availability:

- Fiery XF 7.0.2 is available as an online update via Fiery Server Control for all configurations of Fiery proServer and Fiery XF version 7.
- Alternatively, the version 7.0.2 update can be downloaded from the EFI downloads area:
<http://www.efi.com/products/inkjet-printing-and-proofing/fiery-for-inkjet/fiery-xf/download/>.

Software Maintenance & Support Agreement (SMSA) and EFI Enhanced Service Program (ESP)

EFI Software Maintenance & Support Agreements (SMSA) and Enhanced Service Program (ESP) agreements for Fiery proServer and Fiery XF provide an ongoing stream of features, improvements, fixes and the latest printer drivers. Fiery XF 7 is available at no additional charge for all customers with their Fiery software covered under one of these agreements.

For more information, please contact your local Fiery proServer or Fiery XF dealer, or visit www.efi.com/fiery-for-inkjet. EFI's portfolio of integrated solutions increase productivity and improve your bottom line. Find out more at www.efi.com.