EFI Fiery proServer & Fiery XF version 7.0.4



Fiery Wide Format Products

RELEASE NOTES

EFITM is pleased to announce the release of Fiery[®] proServer and Fiery XF 7.0.4. This latest release is free of charge for all users.

Bug fixes:

- Cutting-related fixes:
 - o Fixed a Colex cutter driver issue that prevented jobs shorter than 16" from being cut correctly.
 - o Fixed a Colex cutter driver issue that mistakenly would introduce a small 0.155mm gap for cuts in between jobs that were set up to have no gap at all.
- Printer-driver-related fixes:
 - Fixed the HP DesignJet 4500 HT printer driver, which previously showed an "Error during input processing".
- JobFlow-related fixes:
 - PDFs sent from Fiery JobFlow to Fiery XF will now correctly show the job title from, for example, Acrobat Reader.
- Fiery XF server-related fixes:
 - o Fixed a server crash issue that was caused by footer usage.
- Nesting-related fixes:
 - o Fixed an issue with automated nestings where the "Process & Hold" command was ignored, and the nesting was processed and printed instead.
- Installer-related fixes:
 - o The Fiery XF updates will now show correct installation dates.

Ink changes and additions:

- Updated and new inks as shown below:
 - o EFI H1625 LED
 - Renamed inks
 - EFI H1625 LED 3M -> INK EFI PROGRAPHICS UV-3M
 - EFI H1625 LED POP -> INK EFI PROGRAPHICS UV POP
 - EFI ProGraphics -> INK EFI PROGRAPHICS UV Rigid
 - Deleted inks
 - EFI R Series UV Ink -> deleted
 - New ink
 - INK EFI PROGRAPHICS UV POP V2

- o H1625-SD
 - Renamed inks
 - EFI SuperDraw UV Inks -> INK EFI SUPERDRAW
- o EFI Pro 16h
 - Renamed inks
 - EFI H1625 LED POP -> INK EFI PROGRAPHICS UV POP
 - EFI Pro 16h -> INK EFI PROGRAPHICS UV-3M
 - EFI ProGraphics -> INK EFI PROGRAPHICS UV Rigid
 - Deleted ink
 - EFI H1625 LED 3M -> deleted
 - New ink
 - INK EFI PROGRAPHICS UV POP V2
- o EFI Pro 24f
 - Renamed inks
 - EFI H1625 LED PO -> INK EFI PROGRAPHICS UV POP
 - EFI Pro 16h -> INK EFI PROGRAPHICS UV-3M
 - EFI ProGraphics -> INK EFI PROGRAPHICS UV Rigid
 - INK EFI PROGRAPHICS UV POP V2
 - Deleted ink
 - EFI H1625 LED 3M -> deleted

New / updated printer driver support:

- New printer drivers
 - o EFI VUTEk 3r+
 - o EFI VUTEk 5r+
- Updated printer driver
 - o VUTEk 3r & 5r
 - Added a new print mode: 4C-5Pass-8S

Software Maintenance & Support Agreement (SMSA) and EFI Enhanced Service Program (ESP)

EFI Software Maintenance & Support Agreements (SMSA) and Enhanced Service Program (ESP) agreements for Fiery proServer and Fiery XF provide an ongoing stream of features, improvements, fixes and the latest printer drivers. Fiery XF 7 is available at no additional charge for all customers with their Fiery software covered under one of these agreements.

For more information, please contact your local Fiery proServer or Fiery XF dealer, or visit www.efi.com/fiery-for-inkjet. EFI's portfolio of integrated solutions increase productivity and improve your bottom line. Find out more at www.efi.com.