FIERY SPECIALTY PRODUCTION

Fiery Digital Factory

11.4 Release Notes

Contents

11.4 Overview

This update brings Fiery Measure integration into the Print Mode Creation and ICC creation processes. Fiery Measure serves to accurately scan printed color charts with supported spectrophotometers, providing improved color output. For additional information, check out the Fiery Measure Help and Documentation article. In addition to Fiery Measure, this update also brings streamlining to the White Ink Limit Wizard, additional device support, and fixes.

New Features

- Fiery Measure is now integrated into Print Mode Creation and ICC creation.
- Added device support for the Epson SC-P7500 Printer.
- Added device support for the MUSE Servo24 and MUSE Servo60 Cutters.
- Added device support for the Quatro Cutter X.
- Added a setting in Tools > Options to allow users to ignore embedded input color profiles in imported files.

Changes and Improvements

- The White Ink Limit Wizard has been reworked to streamline the workflow and improve the clarity of each step to users.
- Auto-loaded ICC files are now automatically cleaned up when the corresponding job is deleted.
- Markup Systems applied to jobs can now be rotated with Auto-Nesting.
- Added an alert to notify users that print modes created in the trial version of Digital Factory will not work in the fully licensed product.

Fixes

- Fixed an issue where the Express Color Wizard would not respect the image size selection when using a custom image.
- Fixed an issue where using Barcode to Find Job with the Zund Marks system to output a PDF file would cause an extra corrupted PDF file to be generated.
- Fixed an issue where contour cut data would not be created for .png files with white content on transparent background.
- Fixed an issue where the cutter port on pre-packaged queues for hybrid devices would not update in the Create Queue Wizard.

Software Support and Requirements

Supported Operating Systems

- Windows 10
- Windows 11

Recommended System Requirements

Operating System	Windows 11
Memory	16gb RAM
Storage Space	SSD with 50gb of available space
CPU	Multicore Intel® or AMD processor, 3GHz or faster
Resolution	1080p

Minimum System Requirements

Operating System	Windows 10
Memory	8gb RAM
Storage Space	HDD with 50gb of available space
CPU	Multicore Intel® or AMD processor, 1.7GHz or faster
Resolution	720p

Fiery Digital Factory 11.4 Release Notes

Network Security

Fiery's Digital Factory includes a variety of features and functions that utilize network communications. Disruptions to the network or incorrect permissions can inhibit the ability to obtain proper drivers or prevent validation of the software. Network permissions should not be modified without the assistance of a network administrator or technical support.

Network Ports

When checking the availability of the network, or installing anti-virus software, make sure the following ports are not blocked.

Port Name	Purpose
80	Device driver downloads
443	HTTPS requests with Fiery server infrastructure

Conclusion

Fiery Specialty Production is proud to deliver these updates to enhance your experience with our software. This release brings new or improved features, important bug fixes, and valuable security patches to ensure optimal performance and safety to make your machines run better.

As always, we appreciate your feedback to help us continue refining and innovating. If you encounter any issues or have suggestions, please reach out to our support team. Thank you for choosing Fiery Specialty Production Applications.