Customer Release Notes

Fiery XF, version 8.0.3

Fiery® is pleased to announce the release of Fiery XF 8.0.3. This latest Fiery software release is a server update for Fiery proServer and Fiery XF 8.0, which updates the Fiery XF server from 8.0, 8.0.1, or 8.0.2 to 8.0.3.

New printer drivers

- EFI

  - Pro 16h+

  - Pro 30f+

- Durst

  - P5 500 (Printer Option Group 7)

- Mimaki

  - CJV330-130 (Printer Option Group 5)

  - CJV330-160 (Printer Option Group 5)

  - JFX600-2513 (Printer Option Group 7)

  - JV330-130 (Printer Option Group 5)

  - JV330-160 (Printer Option Group 5)

  - SWJ-320 (Printer Option Group 5)

- WEIGANG

  - WG S210 Meteor (Printer Option Group 6)

  - WG S210 Royal (Printer Option Group 6)

  - WG S230 W Royal (Printer Option Group 6)

  - WG S350 Meteor (Printer Option Group 6)

  - WG S350 Royal (Printer Option Group 6)

  - WG S350 W V Royal (Printer Option Group 6)

Fixed issues

Fiery XF 8.0.3 related fixes

- Fiery XF server-related fixes:

  - Fixed a problem with slow processing of nesting and step and repeat jobs.

  - Fixed a problem with the character "/" in the printer name. The character prevented the creation of the printer workflow log.

  - Fixed a problem of clear ink dropping out.

  - Fixed a problem with white ink artifacts printed when Zund cut marks are added with a barcode.

- Printer driver-related fixes:

  - Fixed a problem on EPSON SureColor SC-P9500 where a job errors when using Optimize media edge print quality.

  - Fixed a problem for Canon imagePROGRAF GP-6100S where files with Japanese characters in their names did not reach the printer.

  - Fixed a problem on AGFA Titan Jeti where the color on the printout is corrupted when sending jobs with a width of 126 inches to the printer.

  - Fixed a problem on Inkcups Helix in the visual correction curve where clear ink was missing.

  - Fixed a problem on Canon imagePROGRAF PRO-6100 where nestings are not printed.

  - Fixed a problem on EFI VUTEk 32h with white line artifacts.

- Nesting-related fixes:

  - Fixed a problem with nesting with cloned images or copies of the image.

- Step and repeat-related fixes:

  - Fixed a problem in step and repeat of a thin white line in between the copies of seamless step and repeat jobs.

Availability

- The Fiery XF server 8.0.3 update is available as an online update through Fiery Server Control for all configurations of Fiery proServer and Fiery XF version 8.0.

- Alternatively, the Fiery XF server 8.0.3 update can be downloaded from the Fiery Download Center.

Additional notes

- Fiery proServer and Fiery XF solutions are made from multiple software applications. A server application (Fiery XF server), a client application (Fiery Command WorkStation), plus color applications (Color Profiler Option and Color Verifier Option included within Fiery Color Profiler Suite).

- The following overview informs you about the Fiery XF server, Fiery Command WorkStation, and Fiery Color Profiler Suite versions required for the full support of features with Fiery XF 8.0.3:

	Fiery XF server	Fiery Command WorkStation Package	Fiery Color Profiler Suite
Fiery XF 8.0.3	8.0.3	7.0.0.621 or later	5.7.0.10 or later
Supported Operating Systems	Microsoft Windows 10 (64-bit) Microsoft Windows 11 Microsoft Windows Server 2016 (64-bit) Microsoft Windows Server 2019 Microsoft Windows Server 2022	Microsoft Windows 10 (64-bit) Microsoft Windows 11 Microsoft Windows Server 2016 (64-bit) Microsoft Windows Server 2019 Microsoft Windows Server 2022 macOS 10.15 macOS 11 macOS 12 macOS 13 macOS 14	Microsoft Windows 10 (64-bit) Microsoft Windows 11 Microsoft Windows Server 2022 macOS 10.15 macOS 11 macOS 12 macOS 13 macOS 14

- The latest Fiery Command WorkStation and Fiery Color Profiler Suite versions are available through the Fiery Software Manager or the Fiery Download Center in the **Application Software and Tools** section.

Software Maintenance & Support Agreement (SMSA)

Fiery Software Maintenance & Support Agreements (SMSA) for Fiery proServer and Fiery XF provide an ongoing stream of features, improvements, fixes, and the latest printer and cutter drivers. Fiery XF 8.0.3 is available at no additional charge for all customers with their Fiery software covered under this agreement.

For more information, please contact your local Fiery XF dealer or visit https://fiery.com/XF.

Fiery's portfolio of integrated solutions increases productivity and improves your bottom line. Find out more at www.fiery.com.