



Customer Release Notes

Fiery XF, version 9.0.3

Fiery® is pleased to announce the release of Fiery XF 9.0.3. This latest Fiery software release is a server update for Fiery proServer and Fiery XF 9.0, which updates the Fiery XF server from 9.0, 9.0.1, or 9.0.2 to 9.0.3.

New printer drivers

- Canon
 - imagePROGRAF TX-1300 (Printer Option Group 4)
 - imagePROGRAF TX-3300 (Printer Option Group 4)
 - imagePROGRAF TX-3310 (Printer Option Group 4)
 - imagePROGRAF TX-4300 (Printer Option Group 4)
 - imagePROGRAF TX-4310 (Printer Option Group 4)
 - imagePROGRAF TX-5130 (Printer Option Group 4)
 - imagePROGRAF TX-5330 (Printer Option Group 4)
 - imagePROGRAF TX-5331 (Printer Option Group 4)
 - imagePROGRAF TX-5430 (Printer Option Group 4)
 - imagePROGRAF TX-5431 (Printer Option Group 4)

Fixed issue

Fiery XF 9.0.3 related fix

- Fiery XF server-related fix:
 - Fixed an issue where cut paths generated for cutters such as Colex SharpCut and OptiScout did not align with the printed output when a right margin was applied to a nesting or step and repeat job.

Availability

- The Fiery XF server 9.0.3 update is available as an online update through Fiery Server Control for all configurations of Fiery proServer and Fiery XF version 9.0.
- Alternatively, the Fiery XF server 9.0.3 update can be downloaded from the [Fiery Download Center](#).



Additional notes

- Fiery proServer and Fiery XF solutions are made from multiple software applications: a server application (Fiery XF server), a client application (Fiery Command WorkStation), plus color applications (Color Profiler Option and Color Verifier Option included within Fiery Color Profiler Suite).
- The following overview informs you about the Fiery XF server, Fiery Command WorkStation, and Fiery Color Profiler Suite versions required for the full support of features with Fiery XF 9.0.3:

	Fiery XF server	Fiery Command WorkStation Package	Fiery Color Profiler Suite
Fiery XF 9.0.3	9.0.3	7.2.0.664 or later	5.9.1.38 or later
Supported Operating Systems	Microsoft Windows 10 (64-bit) Microsoft Windows 11, 11 24H2, 11 25H2 Microsoft Windows Server 2016 (64-bit) Microsoft Windows Server 2019, 2022, and 2025	Microsoft Windows 10 (64-bit) Microsoft Windows 11 Microsoft Windows Server 2016 (64-bit) Microsoft Windows Server 2019, 2022, and 2025 macOS 13, 14, 15, and 26	Microsoft Windows 10 (64-bit) Microsoft Windows 11 Microsoft Windows Server 2022 and 2025 macOS 13, 14, 15, and 26

- The latest Fiery Command WorkStation and Fiery Color Profiler Suite versions are available through the Fiery Software Manager or the [Fiery Download Center](#) in the **Application Software and Tools** section.

Software Maintenance & Support Agreement (SMSA)

Fiery Software Maintenance & Support Agreements (SMSA) for Fiery proServer and Fiery XF provide an ongoing stream of features, improvements, fixes, and the latest printer and cutter drivers. Fiery XF 9.0.3 is available at no additional charge for all customers with their Fiery software covered under this agreement.

For more information, please contact your local Fiery XF dealer or visit <https://fiery.com/XF>.

Fiery's portfolio of integrated solutions increases productivity and improves your bottom line. Find out more at <https://www.fierey.com>.