



# Fiery Digital Factory

## 12.1.1 Release Notes

---

<b>Fiery Digital Factory 12.1.1 Overview</b> .....	<b>2</b>
Changes and Improvements .....	2
Fixes .....	2
<b>Software Support and Requirements</b> .....	<b>3</b>
Supported Operating Systems .....	3
Recommended System Requirements .....	3
Minimum System Requirements .....	3
<b>Network Security</b> .....	<b>4</b>
Network Ports .....	4
<b>Conclusion</b> .....	<b>4</b>



## Fiery Digital Factory 12.1.1 Overview

This release focuses on resolving user-reported issues and improving overall product stability. The updates included in this release address known issues affecting functionality, usability, and performance to provide a more reliable and consistent experience.

### Changes and Improvements

- Added missing translation items for Simplified Chinese installations.
- Digital Factory no longer minimizes when using Fiery Color Profiler.
- Updated the Digital Factory OPUS Barcode to be compatible with the Summa S Class 3 cutting device.

### Fixes

- Fixed certain text lines that were cut off in Spanish installations.
- Fixed an issue where Spacing Between Copies would not apply when constructing gang sheets.
- Fixed an issue where images at certain resolutions would become enlarged upon import.
- Fixed an issue where linearization charts could appear empty when using certain spot colors.
- Fixed an issue where costing would not work correctly on certain CMYK+ devices.
- Fixed an issue where both the first time run and restart dialogues could appear when reusing an existing activation code.



# Software Support and Requirements

## Supported Operating Systems

- Windows 10
- Windows 11

## Recommended System Requirements

Operating System	Windows 11
Memory	16gb RAM
Storage Space	SSD with 50gb of available space
CPU	Multicore Intel® or AMD processor, 3GHz or faster
Resolution	1080p or 4K

## Minimum System Requirements

Operating System	Windows 10
Memory	8gb RAM
Storage Space	HDD with 50gb of available space
CPU	Multicore Intel® or AMD processor, 1.7GHz or faster
Resolution	720p



## Network Security

Fiery’s Digital Factory includes a variety of features and functions that utilize network communications. Disruptions to the network or incorrect permissions can inhibit the ability to obtain proper drivers or prevent validation of the software. Network permissions should not be modified without the assistance of a network administrator or technical support.

## Network Ports

When checking the availability of the network, or installing anti-virus software, make sure the following ports are not blocked.

Port Name	Purpose
443	Device driver downloads
443	HTTPS requests with Fiery server infrastructure

## Conclusion

Fiery Specialty Production is proud to deliver these updates to enhance your experience with our software. This release brings new or improved features, important bug fixes, and valuable security patches to ensure optimal performance and safety to make your machines run better.

As always, we appreciate your feedback to help us continue refining and innovating. If you encounter any issues or have suggestions, please reach out to our support team. Thank you for choosing Fiery Specialty Production Applications.