



FIERY SPECIALTY PRODUCTION

Fiery Digital Factory

11.3 Release Notes

Contents

Digital Factory 11.3 Overview	2
New Features and Devices	2
Changes and Improvements	3
Fixes	3
Fixes (Continued)	4
Software Support and Requirements	5
Supported Operating Systems	5
Recommended System Requirements	5
Minimum System Requirements	5
Network Security	6
Network Ports	6
Conclusion	6



Digital Factory 11.3 Overview

This update includes a large amount of requested bug fixes, support for additional devices, and new core features such as the Gangsheet Wizard and the Express Color Wizard.

New Features and Devices

The highlights of the new features in this update are the Express Color Wizard and Gangsheet Wizard. The Express Color Wizard is designed to give new users a fast and simple method to generate great looking color profiles for their devices. The Gangsheet Wizard provides even more organization for your queues, allowing users to quickly group jobs for production orders.

- Introduced the Gangsheet Wizard.
- Introduced the Express Color Wizard.
- Added the ability to lock, export, and load settings.
- Added a Print to File toggle switch to the main workspace.
- Added printer support for the following devices:
 - Brother GTX R2R
 - Epson G6000
 - Ricoh DTF
 - Roland TY300
- Added cutter support for the following devices:
 - Mimaki CFX Flatbed
 - Kala cutter markup system
- Added support for the following spectrophotometers:
 - Nix Spectro L
 - X-Rite i1Pro3 Plus with iO Table



FIERY SPECIALTY PRODUCTION

Changes and Improvements

- Improved the interaction between the Variable Data Wizard and images with Contour Cut data.
- Users can now use negative X offset values when adding QR codes. This allows for more customization in QR code page placement.
- Visually improved the UI in the processing options window.
- Improved software tooltips and terminology.
- Added a Disable ICC check box to the ICC Profile page in the Edit Print Mode window.
- Added a Confidence Strips settings tab in the Queue Properties window.
- Improved the wording on warning messages to help clarify the errors that caused them.
- Updated the information displayed in the Product Information Window.
- Added missing translations.
- Added additional functionality to the Secabo DTF MultiCut Pro driver.

Fixes

- Fixed an issue where contour cut lines would not apply properly to non-transparent files.
- Fixed an issue where Costing Data would be saved regardless of the Record Cost Data checkbox status.
- Fixed an issue in which the Queue Background Image would not update immediately in Next-Gen UI.
- Fixed an issue where numerical control boxes would apply changes to the incorrect job when changing selection via mouse click.
- Fixed an issue where the Undo Plug-in Effect button would not work in Next-Gen UI.
- Fixed an issue where job notes would not print despite being enabled.
- Fixed an issue where queue job spacing properties would not apply when creating copies.



FIERY SPECIALTY PRODUCTION

Fixes (Continued)

- Fixed a rare occurrence where printmodes would not properly sync when using Epson devices.
- Fixed an issue where camera settings in the Options menu would not save.
- Fixed an issue where QR codes would not display properly after using Export as PDF or Output PDF.
- Fixed an issue where Print to File would unintentionally switch to a NULL port when using an exported queue.
- Fixed an issue where installing a printer with no ICCs would prevent users from editing the ICC tab.
- Fixed an issue where the Manage Devices menu buttons would sometimes become unintentionally stretched.
- Fixed an issue where Job Costing numbers would be incorrect if a job was moved from the Reserve queue to the Active queue.



FIERY SPECIALTY PRODUCTION

Software Support and Requirements

Supported Operating Systems

- Windows 10
- Windows 11

Recommended System Requirements

Operating System	Windows 11
Memory	16gb RAM
Storage Space	SSD with 50gb of available space
CPU	Multicore Intel® or AMD processor, 3GHz or faster
Resolution	1080p

Minimum System Requirements

Operating System	Windows 10
Memory	8gb RAM
Storage Space	HDD with 50gb of available space
CPU	Multicore Intel® or AMD processor, 1.7GHz or faster
Resolution	720p



FIERY SPECIALTY PRODUCTION

Network Security

Fiery's Digital Factory includes a variety of features and functions that utilize network communications. Disruptions to the network or incorrect permissions can inhibit the ability to obtain proper drivers or prevent validation of the software. Network permissions should not be modified without the assistance of a network administrator or technical support.

Network Ports

When checking the availability of the network, or installing anti-virus software, make sure the following ports are not blocked.

Port Name	Purpose
80	Device driver downloads
443	HTTPS requests with Fiery server infrastructure

Conclusion

Fiery Specialty Production is proud to deliver these updates to enhance your experience with our software. This release brings new or improved features, important bug fixes, and valuable security patches to ensure optimal performance and safety to make your machines run better.

As always, we appreciate your feedback to help us continue refining and innovating. If you encounter any issues or have suggestions, please reach out to our support team. Thank you for choosing Fiery Specialty Production Applications.