



Customer Release Notes

Fiery® proServer and Fiery XF, version 7.2.3

EFI™ is pleased to announce the release of Fiery® proServer and Fiery XF 7.2.3. This latest Fiery software release is a server update for Fiery proServer and Fiery XF 7.2, which updates the Fiery XF server from 7.2, 7.2.1 or 7.2.2 to 7.2.3.

New printer drivers

- EFI
 - Pro 30h
- Agfa
 - Jeti Tauro H3300 LED (Printer Option Super Wide Format)
- EPSON
 - SureColor SC-R50X0 Series* (Printer Option XXL)
 - SureColor SC-R50X0L Series* (Printer Option XXL)

*Fiery Command WorkStation Package 6.6.0.456 or higher is required.

Updated printer drivers

- EFI
 - Pro 32r+
 - Print mode update
 - Removed "Coat-Matte" and "Coat-Matte Production"
 - Added "White-Over High Quality" and "White-Under High Quality"



- EPSON
 - Enhanced EPSON Edge Dashboard functionality including EMX file support without Fiery XF being connected to the EPSON Edge Dashboard for:
 - SureColor SC-F93X0 Series
 - SureColor SC-R50X0/R50X0L Series
 - SureColor SC-S406X0/606X0/806X0 Series
 - "EPSON SureColor SC-P75X0/95X0 Printer Driver AddON" is included in the Fiery XF 7.2.3 update:
 - Printer driver update for EPSON SureColor SC-P75X0/95X0 Series
 - Provides more precise reproduction of small texts through adding:
 - 1200 dpi input resolution for all media types with 1200x1200 dpi or 2400x1200 dpi print modes
 - A new dedicated proofing print mode (1200x1200 dpi/Proofing)

Note: You must apply the latest firmware updates to continue printing.

Bug fixes

FAST RIP-related fixes:

- Fixed a problem with missing parts when a PDF file is printed using Adobe PDF Print Engine.
- Fixed several problems with mirroring.
- Fixed a problem creating correct output for a multipage PDF file.

Printer-driver-related fixes:

- Fixed a problem with cutting a job after printing with Canon imagePROGRAF TX4000 printer driver.
- Fixed a problem retrieving EPLs/ICC with Canon imagePROGRAF iPF64x0 printer driver.
- Fixed a random problem accessing a port when printing on a Canon imagePROGRAF PRO Series printer driver.
- Fixed a problem in writing output data with Inca Onset X3-R printers.
- Fixed a problem printing with a different resolution other than 720x720 dpi on a swissQprint Nyala-2 printer.
- Fixed a problem with printer-related preview file with EFI™ VUTEk 5r [FAST DRIVE] printer driver.
- Fixed a problem printing a profiling job with EFI™ VUTEk 5r [FAST DRIVE] printer driver.
- Fixed a problem publishing when Clear ink is set to Off with EFI™ VUTEk h3/h5 printer driver.
- Fixed a problem printing jobs larger than 4 GB with EFI™ VUTEk 5r+ [FAST DRIVE].
- Fixed a problem printing lines in the output on the right side of a job with EFI™ VUTEk 32h [FAST DRIVE] printer driver.
- Fixed illegal output type error with EPSON Stylus Pro x880 and x800 printer driver series.
- Fixed a problem printing horizontally centered using Canon/Océ Colorado 1640/1650 printers.

Fiery XF server-related fix:

- Fixed a problem in writing workflow log files.

Cutter-driver-related fix:

- Fixed a problem with Eurosystem OptiScout 8 cutter creating the correct tool name in OXF file.

Availability

- The Fiery XF 7.2.3 server update is available as an online update through Fiery Server Control for all configurations of Fiery proServer and Fiery XF version 7.2.
- Alternatively, the Fiery XF 7.2.3 server update can be downloaded from the [EFI downloads area](#).

Additional notes

- Fiery proServer and Fiery XF solutions are made up from multiple software applications. A server application (Fiery XF server), a client application (Fiery Command WorkStation), plus color applications (Color Profiler Option and Color Verifier Option included within Fiery Color Profiler Suite). Only the server application is updated as part of the 7.2.3 update, and the other software components may need to be updated to work correctly with the latest update.
- The following overview informs you about the Fiery XF server, Fiery Command WorkStation, and Fiery Color Profiler Suite versions required for optimal support with Fiery XF 7.2.3:

	Fiery XF server	Fiery Command WorkStation Package	Fiery Color Profiler Suite
Fiery XF 7.2.3	7.2.3	For Windows 10 users: 6.6.0.456 or later For Windows 7 and 8.1 users: 6.5.0.581	5.3.3.22 or later

- The latest versions of Fiery Command WorkStation and Fiery Color Profiler Suite are available through the Fiery Software Manager or the Download Center at <https://www.efi.com/support-and-downloads/download-center> in the Application Software and Tools section.

Software Maintenance & Support Agreement (SMSA) and EFI Enhanced Service Program (ESP)

EFI Software Maintenance & Support Agreements (SMSA) and Enhanced Service Program (ESP) agreements for Fiery proServer and Fiery XF provide an ongoing stream of features, improvements, fixes, and the latest printer drivers. Fiery XF 7.2.3 is available at no additional charge for all customers with their Fiery software covered under one of these agreements.

For more information, please contact your local Fiery proServer or Fiery XF dealer or visit <http://www.efi.com/fiery-for-inkjet>.

EFI's portfolio of integrated solutions increase productivity and improve your bottom line. Find out more at www.efi.com.